Oil Field Environmental Incident Summary

Responsible Party: WIND RIVER TRUCKING, LLC **Well Operator:** WIND RIVER TRUCKING, LLC

Well Name: WIND RIVER SWD 1

Field Name: BEAVER LODGE Well File #: 90209

Date Incident:3/17/2016Time Incident:02:55Facility ID Number:County:WILLIAMSTwp:156Rng:96Sec:15Qtr:

Location Description:

Submitted By: Laurie Rose Received By:

Contact Person: Laurie Rose

947 South 500 East, Ste 100 American Fork, UT 84003

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 5 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None, the spill was contained.

Areal Extent:

Spill was contained.

Potential Environmental Impacts:

None, the spill was contained.

Action Taken or Planned:

Attendant will double check his strap to confirm the level of the tanks.

Wastes Disposal Location: Onsite at Wind River SWD 1

Agencies Involved:

Updates

Date: 3/18/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within diking according to the report. NDIC retains oversight.